### **Dear Custome**r


## **Very important Please Note:**

Your new cabinet has an Infra-red sensor on the bottom of the rear carcass.


There needs to be at least a 15cm gap between the head of the sensor and the nearest obstacle, a wall for example.

If the gap is less than 15cm then your sensor will not work properly!


# IMPORTANT CABINET LOCATION





The line drawings for BL10.100/GR10.100




#### INSTALLATION INSTRUCTIONS













Page 3











Page 4


#### FIXING INSTRUCTIONS FOR THE ADJUSTABLE GLASS SHELVES




Page 5


#### MAGNETIC STRIP INSTALLATION INSTRUCTION








# FIXING INSTRUCTIONS FOR THE MIRROR DOOR (STRONGLY ADVICE TO INSTALL EACH DOOR WITH 2 PERSONS)







3 Door Adjustment

There are two adjustments that can be made (a) ) will adjust the door left to right (b) ) will adjust the gap between the door and the cabinet.

Once you have correctly adjusted the door(s) simply clip on the hinge cover ©)



**CAUTION**: We recommend that you make sure the rear cable is not kinked or overlapped after installation to avoid potentially cracking the internal mirror.



Page 8